

HOSNER CULVERT

Site Number 000101

TOWNLINEROAD (7TH CONCESSION RD), WALSINGHAM

5.0 km W of County Highway 59

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Inventory Data:			
Structure Name	<input type="text" value="Hosner Culvert"/>		
Main Hwy/Road #	<input type="text" value="N WALS - S WALS TL"/>	<input checked="" type="checkbox"/> On <input type="checkbox"/> Under	Crossing Type: <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Navig. Water <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input checked="" type="checkbox"/> Non-Navig. Water
Hwy/Road Name	<input type="text" value="TOWNLIN ROAD (7TH CONCESSION RD), WALSINGHAM"/>		
Structure Location	<input type="text" value="5.0 km W of County Highway 59"/>		
Latitude	<input n"="" type="text" value="42d 39' 56.2"/>	Longitude	<input type="text" value="80d 35' 13.7" w"=""/>
Owner(s)	<input type="text" value="Norfolk County"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> List/not Design. <input type="checkbox"/> Desig. & List <input type="checkbox"/> Cons./not App. <input type="checkbox"/> Desig./not List
MTO Region	<input type="text" value="30"/> Southwestern	Road Class:	<input type="checkbox"/> Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local
MTO District	<input type="text" value="31"/> London / Stratford	Posted Speed	<input type="text" value="80"/> No. of Lanes <input type="text" value="2"/>
Old County	<input type="text" value="20"/> Norfolk	AADT	<input type="text" value="81"/> % Trucks <input type="text"/>
Geographic Twp.	<input type="text" value="585"/> South Walsingham	Inspection Route Sequence	<input type="text"/>
Structure Type	<input type="text" value="15"/> Rigid Frame, Vertical Legs	Interchange Number	<input type="text"/>
Total Deck Length	<input type="text" value="7.1"/> (m)	Interchange Structure Number	<input type="text"/>
Overall Str. Width	<input type="text" value="48"/> (m)	Min. Vertical Clearance	<input type="text" value="3"/> (m)
Total Deck Area	<input type="text" value="340.8"/> (m ²)	Special Route	<input type="checkbox"/> Truck <input type="checkbox"/> Emergency <input type="checkbox"/> School <input type="checkbox"/> Bicycle
Roadway Width	<input type="text" value="14"/> (m)	Detour Length Around Bridge	<input type="text" value="10"/> (km)
Skew Angle	<input type="text"/> (Degrees)	Direction of Structure	<input type="text" value="North / South"/>
No. of Spans	<input type="text" value="1"/>	Fill on Structure	<input type="text" value="6"/> (m)
Span Length	<input type="text" value="6.1"/> (m)		

Historical Data:			
Year Built	<input type="text" value="1964"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text" value="May 23, 2014"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text" value="/ /"/> (tonnes)
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		
Rehab History: (Date/description)			

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Field Inspection Information:		
Date of Inspection:	July 12, 2016	Type of Inspection: <input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Matt Alderson, G. Douglas Vallee Ltd.	
Others in Party:	N/A	
Access Equipment Used:	Hammer, Binoculars, Measuring Tape, Camera, etc.	
Weather:	Sunny	
Temperature:	30 °C	

Additional Investigation Required:	Priority		
	None	Normal	Urgent
Material Condition Survey			
<input checked="" type="checkbox"/> Detailed Deck Condition Survey:		X	
<input checked="" type="checkbox"/> Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
<input checked="" type="checkbox"/> Concrete Substructure Condition Survey:	X		
<input checked="" type="checkbox"/> Detailed Coating Condition Survey:	X		
<input checked="" type="checkbox"/> Detailed Timber Investigation	X		
<input checked="" type="checkbox"/> Post-Tensioned Strand Investigation	X		
Underwater Investigation:	X		
Fatigue Investigation:	X		
Seismic Investigation:	X		
Structure Evaluation:		X	
Monitoring			
<input checked="" type="checkbox"/> Monitoring of Deformations, Settlements and Movements:	X		
<input checked="" type="checkbox"/> Monitoring Crack Widths:	X		
Investigation Notes: No signs or barriers.			

Overall Structure Notes:	
Recommended Work on Structure:	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> Maintenance <input type="checkbox"/> Major Rehab.
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years
Overall Comments:	Remove large trees and repair culvert ends.
Date of next Inspection:	July 12, 2018

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 07 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 08 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 09 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 10 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 11 Deck drainage | 16 Other |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and swing bridge maintenance | 07 Repair to structural steel | 13 Erosion control at bridges |
| 02 Bridge cleaning | 08 Repair of bridge concrete | 14 Concrete sealing |
| 03 Bridge handrail maintenance | 09 Repair of bridge timber | 15 Rout and seal |
| 04 Painting steel bridge structures | 10 Bailey bridges - maintenance | 16 Bridge deck drainage |
| 05 Bridge deck joint repair | 11 Animal/pest control | 17 Scaling (Loose concrete or ACR steel) |
| 06 Bridge bearing maintenance | 12 Bridge surface repair | 18 Other |

Rehabilitation Required:		Element	Priority				Estimated Construction Cost
Rehab	Replace		Urgent	Within 1 yr	1-5 yrs	6-10 yrs	
		Approaches Drainage (app)					
		Wearing Surface (Approaches)					
		Barrels					
X		Inlet Components			X		\$10,000
		Outlet Components					
		Streams and Waterways					
		Foundation (below ground level)					
						Total Cost	\$10,000

Associated Work:	Comments	Estimated Construction Cost
Additional Investigations		
Traffic Management		
Utilities		
Road Allowance		
Environmental Assessment		
Engineering		
Other		
Contingencies		
Total Cost		\$0

Justification:		
Notes:	Construction Cost:	\$10,000
	Associated Work Cost:	\$0
	TOTAL Estimated Cost:	\$10,000

Ontario Structure Inspection Manual - Inspection Form

Site Number: 000101

Element Data

Element Group:		1600 Approaches				Length:		
Element Name:		1603 Approaches Drainage (app)				Width:		
Location:		North and South				Height:		
Material:						Count:		1
Element Type:						Total Quantity:		1 Each
Environment:		Moderate				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	Each	0	1	0	0			
Comments:								
Catch basin piped over slopes. No signs or barriers.								
Recommended Work:				Rehab <input type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input type="checkbox"/>		
Maintenance Needs:				<input type="checkbox"/>		Urgent <input type="checkbox"/>		
						1 year <input type="checkbox"/>		
						2 year <input type="checkbox"/>		

Element Group:		1600 Approaches				Length:		
Element Name:		1601 Wearing Surface (Approaches)				Width:		
Location:		Top of Fill				Height:		
Material:						Count:		1
Element Type:						Total Quantity:		1 Each
Environment:		Severe				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	Each	0	1	0	0			
Comments:								
Material is tar and chip. Transverse cracking along center line of culvert.								
Recommended Work:				Rehab <input type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input type="checkbox"/>		
Maintenance Needs:						Rout & Seal		
						<input type="checkbox"/>		
						Urgent <input checked="" type="checkbox"/>		
						1 year <input type="checkbox"/>		
						2 year <input type="checkbox"/>		

Element Group:		1200 Culverts				Length:		48
Element Name:		1203 Barrels				Width:		6.1
Location:		North				Height:		3
Material:		4 Cast-in-place Concrete				Count:		1
Element Type:						Total Quantity:		878.4 sq.m
Environment:		Benign				Limited Inspection:		X
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	sq.m	0	0	875.4	3			
Comments:								
Limited inspection due to access. Remove large trees on ends. Delamination on north end soffit. Possible delamination on south end soffit. Limited inspection at South end.								
Recommended Work:				Rehab <input type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input type="checkbox"/>		
Maintenance Needs:						Repair of Bridge Concrete		
						<input type="checkbox"/>		
						Urgent <input checked="" type="checkbox"/>		
						1 year <input type="checkbox"/>		
						2 year <input type="checkbox"/>		

Ontario Structure Inspection Manual - Inspection Form

Site Number: 000101

Element Data

Element Group:		1200 Culverts				Length:		
Element Name:		1201 Inlet Components				Width:		7
Location:		North End				Height:		3
Material:		4 Cast-in-place Concrete				Count:		2
Element Type:						Total Quantity:		42 sq.m
Environment:		Moderate				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	sq.m	0	0	36	6			
Comments:								
Efflorescence and delamination showing on north and south wall faces .Cracking noted.								
Recommended Work:				Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/>		Maintenance Needs:		
Timing:				Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input checked="" type="checkbox"/> 6 - 10 yr <input type="checkbox"/>		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:		1200 Culverts				Length:		
Element Name:		1202 Outlet Components				Width:		7
Location:		South End				Height:		3
Material:		4 Cast-in-place Concrete				Count:		2
Element Type:						Total Quantity:		42 sq.m
Environment:		Moderate				Limited Inspection:		X
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	sq.m	0	0	36	6			
Comments:								
Limited inspection due to access.								
Recommended Work:				Rehab <input type="checkbox"/> Replace <input type="checkbox"/>		Maintenance Needs:		
Timing:				Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Element Group:		1400 Embankments & Streams				Length:		
Element Name:		1401 Streams and Waterways				Width:		
Location:						Height:		
Material:						Count:		1
Element Type:						Total Quantity:		1 Each
Environment:						Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	Each	0	0	1	0			
Comments:								
Slopes are steep and grown over.								
Recommended Work:				Rehab <input type="checkbox"/> Replace <input type="checkbox"/>		Maintenance Needs:		
Timing:				Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>		<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year		

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Element Data

Element Group:	1300 Foundations					Length:	
Element Name:	1301 Foundation (below ground level)					Width:	
Location:						Height:	
Material:						Count:	
Element Type:						Total Quantity:	
Environment:						Limited Inspection:	X
Protection System:	Unknown					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor		
Comments: Limited inspection, not visible.							
Recommended Work: Rehab <input type="checkbox"/> Replace <input type="checkbox"/>						Maintenance Needs:	
Timing: Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>						<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	



Figure 1 East Approach



Figure 2 West Approach



Figure 3 North Profile



Figure 4 Upstream



Figure 5 Downstream



Figure 6 Barrel, Looking South



Figure 7 Efflorescence & Deterioration at Inlet Fascia



Figure 8 Transverse Crack in Wearing Surface