

DEDRICK CREEK CULVERT

Site Number 971601

NORFOLK 16, ST. WILLIAMS ROAD, CHARLOTTEVILLE

1.7 km N of Norfolk Highway 24

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Inventory Data:			
Structure Name	<input type="text" value="Dedrick Creek Culvert"/>		
Main Hwy/Road #	<input type="text" value="FORESTRY FARM RD"/>	<input checked="" type="checkbox"/> On <input type="checkbox"/> Under	Crossing Type: <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Navig. Water <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input checked="" type="checkbox"/> Non-Navig. Water
Hwy/Road Name	<input type="text" value="NORFOLK 16, ST. WILLIAMS ROAD, CHARLOTTEVILLE"/>		
Structure Location	<input type="text" value="1.7 km N of Norfolk Highway 24"/>		
Latitude	<input n"="" type="text" value="42d 42' 33.6"/>	Longitude	<input type="text" value="80d 26' 52.8" w"=""/>
Owner(s)	<input type="text" value="Norfolk County"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./not App. <input type="checkbox"/> List/not Design. <input type="checkbox"/> Design./not List <input type="checkbox"/> Desig. & List
MTO Region	<input type="text" value="30"/> Southwestern	Road Class:	<input type="checkbox"/> Freeway <input type="checkbox"/> Arterial <input checked="" type="checkbox"/> Collector <input type="checkbox"/> Local
MTO District	<input type="text" value="31"/> London / Stratford	Posted Speed	<input type="text" value="80"/> No. of Lanes <input type="text" value="2"/>
Old County	<input type="text" value="20"/> Norfolk	AADT	<input type="text" value="1953"/> % Trucks <input type="text"/>
Geographic Twp.	<input type="text" value="1119"/> Charlotteville	Inspection Route Sequence	<input type="text"/>
Structure Type	<input type="text" value="12"/> Rectangular Culvert	Interchange Number	<input type="text"/>
Total Deck Length	<input type="text" value="7"/> (m)	Interchange Structure Number	<input type="text"/>
Overall Str. Width	<input type="text" value="18.5"/> (m)	Min. Vertical Clearance	<input type="text" value="1.3"/> (m)
Total Deck Area	<input type="text" value="129.5"/> (m ²)	Special Route	<input type="checkbox"/> Truck <input type="checkbox"/> Emergency <input checked="" type="checkbox"/> School <input type="checkbox"/> Bicycle
Roadway Width	<input type="text" value="10.4"/> (m)	Detour Length Around Bridge	<input type="text" value="9"/> (km)
Skew Angle	<input type="text"/> (Degrees)	Direction of Structure	<input type="text" value="East / West"/>
No. of Spans	<input type="text" value="1"/>	Fill on Structure	<input type="text" value="1.2"/> (m)
Span Length	<input type="text" value="6.2"/> (m)		

Historical Data:			
Year Built	<input type="text" value="1955"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text" value="July 2, 2014"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text" value="/ /"/> (tonnes)
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		
Rehab History:	(Date/description)		

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Field Inspection Information:		
Date of Inspection:	July 19, 2016	Type of Inspection: <input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Matt Alderson, G. Douglas Vallee Ltd.	
Others in Party:	N/A	
Access Equipment Used:	Hammer, Binoculars, Measuring Tape, Camera, etc.	
Weather:	Sunny	
Temperature:	26 °C	

Additional Investigation Required:	Priority		
	None	Normal	Urgent
Material Condition Survey			
<input checked="" type="checkbox"/> Detailed Deck Condition Survey:		X	
<input checked="" type="checkbox"/> Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
<input checked="" type="checkbox"/> Concrete Substructure Condition Survey:	X		
<input checked="" type="checkbox"/> Detailed Coating Condition Survey:	X		
<input checked="" type="checkbox"/> Detailed Timber Investigation	X		
<input checked="" type="checkbox"/> Post-Tensioned Strand Investigation	X		
Underwater Investigation:	X		
Fatigue Investigation:	X		
Seismic Investigation:	X		
Structure Evaluation:	X		
Monitoring			
<input checked="" type="checkbox"/> Monitoring of Deformations, Settlements and Movements:	X		
<input checked="" type="checkbox"/> Monitoring Crack Widths:	X		
Investigation Notes:	No barriers. On geographic townline - Charlottetown and North Walsingham. Utility attached to West face, casing is broken. (2014)		

Overall Structure Notes:	
Recommended Work on Structure:	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Replace <input type="checkbox"/> Maintenance <input type="checkbox"/> Major Rehab.
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years <input checked="" type="checkbox"/> 6 to 10 years
Overall Comments:	
Date of next Inspection:	July 19, 2018

Suspected Performance Deficiencies

- | | | |
|--|---|-------------------------------------|
| 01 Load carrying capacity | 07 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 08 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 09 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 10 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 11 Deck drainage | 16 Other |

Maintenance Needs

- | | | |
|---|--|---|
| 01 Lift and swing bridge maintenance | 07 Repair to structural steel | 13 Erosion control at bridges |
| 02 Bridge cleaning | 08 Repair of bridge concrete | 14 Concrete sealing |
| 03 Bridge handrail maintenance | 09 Repair of bridge timber | 15 Rout and seal |
| 04 Painting steel bridge structures | 10 Bailey bridges - maintenance | 16 Bridge deck drainage |
| 05 Bridge deck joint repair | 11 Animal/pest control | 17 Scaling (Loose concrete or ACR steel) |
| 06 Bridge bearing maintenance | 12 Bridge surface repair | 18 Other |

Ontario Structure Inspection Manual - Inspection Form

Site Number: 971601

Rehabilitation Required:		Element	Priority				Estimated Construction Cost
Rehab	Replace		Urgent	Within 1 yr	1-5 yrs	6-10 yrs	
		Wearing Surface (Approaches)					
		Barrels					
X		Inlet Components				X	\$15,000
X		Outlet Components				X	\$15,000
		Streams and Waterways					
		Foundation (below ground level)					
		Sign					
						Total Cost	\$30,000

Associated Work:	Comments	Estimated Construction Cost
Additional Investigations		
Traffic Management		
Utilities		
Road Allowance		
Environmental Assessment		
Engineering		
Other		
Contingencies		
		Total Cost
		\$0

Justification:		
Notes:		
	Construction Cost:	\$30,000
	Associated Work Cost:	\$0
	TOTAL Estimated Cost:	\$30,000

Ontario Structure Inspection Manual - Inspection Form

Site Number: 971601

Element Data

Element Group:		1600 Approaches				Length:		
Element Name:		1601 Wearing Surface (Approaches)				Width:		
Location:		Top of Fill				Height:		
Material:						Count:		2
Element Type:						Total Quantity:		2 Each
Environment:		Severe				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	Each	0	2	0	0			
Comments:								
Sealed cracks at South structure edges. Unsealed cracks throughout wearing surface.								
Recommended Work:				Rehab <input type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input type="checkbox"/>		
				Maintenance Needs:				
				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year				

Element Group:		1200 Culverts				Length:		18.5
Element Name:		1203 Barrels				Width:		8.8
Location:						Height:		
Material:						Count:		1
Element Type:						Total Quantity:		162.8 sq.m
Environment:		Moderate				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	sq.m	0	0	162.8	0			
Comments:								
Recommended Work:				Rehab <input type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input type="checkbox"/>		
				Maintenance Needs:				
				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year				

Element Group:		1200 Culverts				Length:		7
Element Name:		1201 Inlet Components				Width:		0.4
Location:		East				Height:		1.3
Material:						Count:		1
Element Type:						Total Quantity:		3.6 sq.m
Environment:		Moderate				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition	Units	Exc.	Good	Fair	Poor			
Data:	sq.m	0	0	1	2.6			
Comments:								
Deterioration of fascia. Efflorescence and spalling present. Slope above culvert is eroding. Overgrown.								
Recommended Work:				Rehab <input checked="" type="checkbox"/>		Replace <input type="checkbox"/>		
Timing:				Urgent <input type="checkbox"/>		< 1yr <input type="checkbox"/>		
				1 - 5 yr <input type="checkbox"/>		6 - 10 yr <input checked="" type="checkbox"/>		
				Maintenance Needs:				
				Repair of Bridge Concrete, E				
				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year				

Ontario Structure Inspection Manual - Inspection Form

Site Number: 971601

Element Data

Element Group:		1200 Culverts				Length:		7
Element Name:		1202 Outlet Components				Width:		0.4
Location:		West				Height:		1.3
Material:						Count:		1
Element Type:						Total Quantity:		3.6 sq.m
Environment:		Severe				Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor			
	sq.m	0	0	0	3.6			
Comments:								
Severe deterioration and delamination. Utility present and casing is broken. Slope above culvert is eroding. Limited inspection due to overgrowth.								
Recommended Work:				Maintenance Needs:				
Rehab <input checked="" type="checkbox"/> Replace <input type="checkbox"/>				Bridge Concrete Repair				
Timing: Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input checked="" type="checkbox"/>				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input checked="" type="checkbox"/> 2 year				

Element Group:		1400 Embankments & Streams				Length:		
Element Name:		1401 Streams and Waterways				Width:		
Location:						Height:		
Material:						Count:		1
Element Type:						Total Quantity:		1 Each
Environment:						Limited Inspection:		
Protection System:		Unknown				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor			
	Each	0	0.75	0.25	0			
Comments:								
Build up of stream bed material along North wall of culvert.								
Recommended Work:				Maintenance Needs:				
Rehab <input type="checkbox"/> Replace <input type="checkbox"/>								
Timing: Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year				

Element Group:		1300 Foundations				Length:		
Element Name:		1301 Foundation (below ground level)				Width:		
Location:						Height:		
Material:						Count:		1
Element Type:						Total Quantity:		1
Environment:						Limited Inspection:		X
Protection System:		Unknown				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor			
Comments:								
Not visible.								
Recommended Work:				Maintenance Needs:				
Rehab <input type="checkbox"/> Replace <input type="checkbox"/>								
Timing: Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>				<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year				

Ontario Structure Inspection Manual - Inspection Form

Site Number:

Element Data

Element Group:	1500 Signs					Length:	
Element Name:	1501 Sign					Width:	
Location:						Height:	
Material:						Count:	4
Element Type:						Total Quantity:	4 Each
Environment:						Limited Inspection:	
Protection System:	Unknown					Perform. Deficiencies	
Condition Data:	Units Each	Exc. 0	Good 4	Fair 0	Poor 0		
Comments:							
Recommended Work:						Maintenance Needs:	
Rehab <input type="checkbox"/> Replace <input type="checkbox"/> Timing: Urgent <input type="checkbox"/> < 1yr <input type="checkbox"/> 1 - 5 yr <input type="checkbox"/> 6 - 10 yr <input type="checkbox"/>						<input type="checkbox"/> Urgent <input type="checkbox"/> 1 year <input type="checkbox"/> 2 year	



Figure 1 North Approach



Figure 2 South Approach



Figure 3 East Profile, Inlet



Figure 4 West Profile, Outlet



Figure 5 Upstream



Figure 6 Downstream



Figure 7 Barrel, Looking West



Figure 8 East Fascia Deterioration, Efflorescence & Stalactites



Figure 9 West Fascia Deterioration



Figure 10 Cracks in Wearing Surface